

Lake Name: Kambhipura Govt. Karabu Kere-2

Date of Visit: 11.02.2016

Lake Name: Kambhipura Govt. Karabu Kere-2


BASIC INFORMATION				
Other Name : Nil		EMPRI Code: BUBSKGkmp_kr3-1200		Maximum Depth (m): 2
District Name: Bengaluru Urban		MI Tank Reg. No.: Nil		
Taluk Name : Bengaluru South		Year of Creation : 1890		Geographical Coordinates
Hobli Name : Kengeri		Year of Rejuvenation : Nil		Lat. 12°53'16.0"N
Village Name	Survey No.	Extent Area (A-G)	Source	Long. 77°28'05.7"E
Kambipura	70	5.13	RTC	Preservation Authority
Total Extent (A-G)		5.13	-	ZP
MORPHOLOGY	WATER QUALITY		HYDROLOGY	
Elevation(m) : 780	Temperature (°C)	Dry		Status : Clean
Inlet Drain : 2	pH	Dry		Type : Seasonal
Waste weir : Nil	Conductivity (µS/cm)	Dry		Source of water : Rainfall
Sluice gate : Nil	Light Transparency (m)	Dry		Upstream water body : Nil
Fence : Wall & Thorn wire	TSS (mg/l)	Dry		Downstream water body: Nil
	TDS (mg/l)	Dry		
	Turbidity (NTU)	Dry		
	DO (mg/l)	Dry		
Culverts : 2	BOD (mg/l)	Dry		Nature of Catchment : Urban
Check dam : Nil	COD (mg/l)	Dry		
Road : 2	TKN (mg/l)	Dry		
Surrounding Area: Plantation, Vacant land & Apartment	Phosphate (mg/l)	Dry		Date of Visit : 16.02.17
	Total Coliform (MPN/100ml)	Dry		
BIOTIC DATA		SOCIO-ECONOMIC VALUE		
Vegetation Cover : Partial		Drinking Water : Not Observed		
Vegetation Type : Growing on bank		Washing : Not Observed		
Aquatic Flora : Emergent		Bathing : Not Observed		
Fauna : Birds, Butterfly & Dragonfly		Livestock Management : Not Observed		
		Irrigation : Not Observed		
		Fishing : Not Observed		
Amphibian : Not Observed		Cultural Activities : Not Observed		
Reptile : Not Observed		Recreational Activity : Not Observed		
Mammals : Not Observed		Others Uses : Not Observed		
THREATS				
Direct Point Source Pollutants	: Dumping for Garbage, Construction Debris & Poultry Waste			
Indirect Point Source Pollutants	: Nil			
Quantity of Sewage Inflow (Cumecs)	: No			
Encroachment	: Road (2%)			
Soil Excavation	: No			
Weeds	: Partial			

Conservation Strategies		
S. No.	Issues	Strategies
1	Waste dumping	Fence the lake and create awareness
2	Encroachment	Survey by consent Authority & evict the encroachment





EMPRI Cartography for Kambhipura Govt. Karabu Kere-2




Disclaimer:

- Lake Cartography is for visual purpose only, which describes the features at the time of visit and not to scale.
- Encroachment of lake is only indicative. It needs to be verified with Department of Survey Settlement and Land Records (SSLR), Government of Karnataka.
- This is put out for general information of public at large, so the information is not usable to determine any boundary. Accordingly, the map information is indicative & user shall oneself verify as per prescribed legal procedure the actual boundaries of the survey number. No claim based on this information shall be entertained by the Government or any of its Departments.
- This information is for indicative purpose and is not usable for any legal purposes. Any use by anyone shall be at their own risk and cost.

EMPRI

SSLR Surveyed Map for Kambhipura Govt. Karabu Kere-2



SSLR surveyed lake map was downloaded from <http://landrecords.karnataka.gov.in/revenuemaps/lakesurvey.aspx>